

## Software Update History



### Version 1.1.2 (June 2015):

- Fixed microphone polarity inversion when switching on the device with mic/line selection or when changing buffer settings at run-time. This fix is only relevant for devices starting with S/N 12-...

### Version 1.1.1 (Apr 2013):

- Fixed microphone signal polarity problem. This fix is only relevant for devices starting with S/N 12-... (rolled-out since December 2012). Without this fix these devices show a reversed signal polarity of microphone signals compared to line input signals.

### Version 1.1.0 (Nov 2012):

- Samplerates 44100, 48000, 88200 and 96000 are now supported
- Improved audio stream robustness
- Minor bug fixes:
  - o Quickly changing Lineout software attenuation wasn't followed correctly by headphone
  - o Removed "dropped"-message after disconnecting from device

### Version 1.0.7 (Aug 2012):

- Fixes non-persistence of 44.1 kHz sample rate setting
- Disabling control dial push action re-setting to 0 dB gain if line outputs

### Version 1.0.5 (Nov 2011)

- Initial release